Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080190-3

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128122

RECEIVED FROM

DATE REC'D 1-17-57

P. O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. / S. O. NO.

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
1	732602-[illegible] 32 - RELAYS	✓		
	LATCH PLT. 53055			

RECEIVED BY

INSPECTED BY

DATE 1/17/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No.128123

RECEIVED FROM

DATE REC'D 1-17-57

P. O. NO.

VENDOR PACKING SLIP NO.

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W. O. NO. / S. O. NO.

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
2	732644 MOUNT PLATE	2 ✓		
	LAT. R PLT. 53055			

RECEIVED BY

INSPECTED BY

DATE 1/17/57

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080190-3